



Historic Shipping on the River Murray

CHAPTER 6 Conservation Assessment

Introduction

One of the most useful ways of assessing wreck sites for management purposes is through obtaining data on rates of deterioration in the vessel fabric. This enables contributing factors in weathering and corrosion to be established, and through control of environmental parameters (e.g. through the attachment of a sacrificial anode, reburial or sand bagging of a wreck) it is possible to stabilise a vessel's disintegration.

The corrosion data collected on a number of wreck sites in the River Murray forms the basis for comparative analysis on the deterioration/preservation of riverine submerged sites. While such data collection has been collated for wreck sites at sea, this riverine survey is the first of its type in Australia, and should be of great benefit to maritime archaeological practitioners in other states and individuals concerned with assessing the condition of a vessel *in situ*.

The wrecks investigated were chosen for several purposes. Where construction materials were similar assessment could help highlight differences in environment both locally and throughout the river and the differing effects from length of inundation. Where two vessels of dissimilar construction materials occurred within the same environmental constraints, differing effects of these parameters on the fabric of each vessel could be assessed. Both deep water sites and partially submerged sites were represented. The field work techniques involved in the data collection are outlined in Chapter 1.

The following section was prepared by Dr Ian MacLeod (Materials Conservation Department at the Western Australian Museum), as consultant to the 'historic shipping on the River Murray' project.

Report on the Corrosion of Shipwrecks in the River Murray

ALBION: Goolwa

The *Albion* was a barge in the River Murray which had a timber hull with iron sides topped by wooden planking. It was apparently a government

vessel that was unregistered. It is currently settled on the bottom of the river in about two metres of water adjacent to a reed bank and the stem post is within half a metre of a new wooden jetty upstream of the location of the *Uranus* at Goolwa. The stem post appears to be made of red gum (*Eucalyptus camaldulensis*) and it was covered with a thin layer of green algal slime. A measurement of the pH of the river water was taken and was found to be 7.90.

Table 6: pH profile of red gum on the *Albion*

Location	pH	Depth into wood mm.
Stem post	7.90	0
"	7.12	2
"	7.45	3
"	7.50	3.5
Upper planking	7.05	3
"	7.02	3

It was impossible to penetrate the wood any further than the depths indicated in the table. Beyond the indicated depths, the original colour of the red gum was exposed and the flattened profile of the 10 mm diameter drill bit could not penetrate the undegraded wood. The maximum difference of 0.88 pH units between the wood and the surrounding water is indicative of the neutralising ability of the timbers acidic units (e.g. acetate units) to respond to the alkalinity of the surrounding waters. Since pH is a logarithmic function the difference of 0.88 in the pH value corresponds to a factor of 7.6 times difference in the analytical concentration of the hydrogen ions. The variability of the data from the stem post is due to experimental difficulties in locating the glass electrode on the area of freshly exposed materials. The pH profile of the wood is approximately -0.25 pH.mm-1 for the upper planking and -0.39 pH.mm-1 for the first two millimetres of the stem post.

Conservation Assessment

A corrosion survey on the iron fittings of the wreck was undertaken in order to ascertain the inherent corrosivity of the site. The stern section of the upper iron plating had a purplish-blue patina to it that was very reminiscent of an iron-tannate complex. This area was found 10 cm above the green algal slime line and may be due to complexation of the iron corrosion products reacting with soluble tannates in the water that came from the vegetation that had fallen into or grew on the river banks. The bulkhead in the midships was corroded right through in the area that was within 20 cm of the water line. In general only the heavier iron structural supports, in the form of frames, have survived above the waterline. The results of the corrosion survey are listed in Table 7.

Table 7 : Corrosion potentials of iron fittings on the *Albion*

Fitting	Ecorr. volts vs. Ag/AgCl	Ecorr. volts vs. NHE
Plating near port bow	-0.552	-0.168
First bulkhead	-0.568	-0.214
"T" shaped frame near outer plating	-0.517	-0.163
Midships plating	-0.514	-0.160
Plating near stern	-0.462*	-0.018

* This plating was apparently in electrical contact with the "tannate" patinated material near the stern section of the vessel and the corrosion potential may be moved in the anodic direction through the formation of a passive film. Laboratory studies are needed to elucidate the cause of this effect. The voltage of the flow-through Ag/AgCl reference electrode was calibrated at +0.354 volts vs. NHE.

The average corrosion potential of the iron plating was -0.163 ± 0.005 volts while the bulkhead was -0.214 volts which is indicative of the fact that the major part of the bulkhead is well below the water interface and as such the lower level of dissolved oxygen will result in a slower corrosion rate. The higher corrosion potential of the plating is due to the structure of the vessel which consists of an upper wooden planking above a steel plating

section which in turn was above a wooden section that came up from the bottom of the vessel. The average corrosion potential of all the iron materials was -0.176 volts vs. NHE. The apparent contamination of the river water with sea water is reflected in the pH which was only 0.22 units less alkaline than the open sea value measured in the Port Adelaide River at 8.12. The sites at Goolwa were only 12.8 km (8 miles) from the river mouth. The effectiveness of the barrage system in the river is indicated by the low reading of the chloride content of the water which was 410 ppm which is one forty sixth of the amount in normal sea water.

URANUS: Goolwa

The *Uranus* was built in 1886 as a barge and currently lies in the River Murray in a partly submerged condition; it has been built around by two arms of a modern jetty in front of the remains of the stern wheeler the *Captain Sturt* at Goolwa. It was sunk to form a breakwater. Some of the structure above the waterline remains but most of the vessel lies in a highly corroded state. The vessel has been in its current location for approximately fifty years. The results of the corrosion survey are listed in Table 8. The water temperature at both sites at Goolwa was between 10.5 and 11°C.

Table 8: Corrosion data from the wreck of the *Uranus*

Fitting	Ecorr. volts vs. Ag/AgCl	Ecorr. volts vs. NHE	pH
Stem post	-	-	7.42
Stern post	-	-	7.20
Rub rail	-0.516	-0.162	7.41
Plating at bow	-0.513	-0.159	-
Plating at stern	-0.511	-0.157	6.46
Plating near stern	-0.528	-0.174	-

The build-up of a mixture of corrosion products and the slime around and below the waterline, near the stern, had allowed a 1 cm layer of concretion-corrosion matrix to develop. This obviously facilitated the pH gradient from the water value of 7.92 to 6.46 at the corrosion product-water interface approximately 20 cm below the water line. The wood on the *Uranus* appeared to be

Conservation Assessment

more degraded than on the *Albion* although this is not reflected in different pH values - it should be noted that the original colour of the *Uranus* timber had not yet been exposed at a depth of 3 mm into the surface. The average corrosion potential for the iron plating on the *Uranus* is -0.163 ± 0.008 volts vs. NHE which is 13 mV more positive (less negative) than the average value for the iron plating found on the *Albion*. The small difference in the average voltage of the vessel is probably a reflection of the location of the *Uranus* in the breakwater system which has more water flow around it than the *Albion* has in its location adjacent to the river bank. The recording of the pH profile on the wood from the *Uranus* stern post is seen in Figure 104.




Figure 104 Measurement of surface pH of wooden stem post in the *Uranus* (1992)

CROWIE: Morgan

The *Crowie* is a composite wood and iron River Murray barge that was built in 1911 and may have been abandoned as early as 1946 along with the *Corowa* with which it was commonly associated. The vessels are near Morgan and are located close to the 199 mile mark from the river mouth. The register closed in 1961. The remains of the vessel lie parallel to the shore line and approximately ten metres from the bank. Only the ribs stand proud of the water with stern deck plating lying about 15 cm below the water line. A corrosion survey showed up interesting results that relate to not only metal sections that have part of their area exposed but also to metal sections that were fully immersed in the water. The temperature at a depth of one metre was 11.3°C while the temperature on the bottom at 6m was only marginally lower at 11°C . The results of the measurements are shown in Table 9.

Table 9: Iron corrosion potentials on the barge *Crowie*.

Fitting	Ecorr.* volts vs. Ag/AgCl	Ecorr. volts. vs NHE
Port beam	-0.523	-0.149
Iron decking plate	-0.521	-0.147
Outside hull plate	-0.510	-0.136
Frame, port side	-0.495	-0.121
Totally submerged frame	-0.554	-0.180
Submerged frame near bow	-0.547	-0.173
Submerged stern plating	-0.522	-0.148
Stern deck beam	-0.517	-0.145

* The potential of the flowing water Ag/AgCl electrode from the NSW Department of Planning had a potential of $+0.374$ volts vs. NHE.

The average of all the corrosion potential measurements was -0.150 ± 0.019 volts vs. NHE and as such the voltage is indicative of a slightly elevated corrosion rate compared with the two vessels located at Goolwa. The increased amount of the iron structure that was exposed and the greater amount of water movement all contribute to the differences in the measurements. The only totally submerged iron frame that was measured was 36 mV more negative in corrosion potential than the average value of the other frames that were partly exposed. The chloride concentration in the water at Morgan was 185 ppm compared with 410 ppm at Goolwa.

P.S. COROWA: Morgan

The remains of the 1868 paddle steamer *Corowa*, which was abandoned at Morgan on the River Murray in 1946 after sinking, lies about 15 metres from the shore on the town side of the river. Part of the stern wheel lies above the water and a small section of a steam-pipe lies proud of the water to a height of about 10 cm, as can be seen in Figure 105. A corrosion survey of the vessel and its remains was made using the AGA full face mask with communication facilities to facilitate the coordination of measurements and the recording of the data, which is summarised below in Table 10. A divers knife was used to clear a small area of the surface and a torch showed up the white metal where the platinum electrode was placed. Without the use of the torch it would have been impossible to accurately place the electrode and ensure good electrical contact.

Conservation Assessment



Figure 105 Bill Jeffery inspecting the steam pipe from the *Corowa* engine.

Table 10: Corrosion potentials for the *Corowa*.

Fitting	E _{corr.} * volts vs. Ag/AgCl	E _{corr.} volts vs. NHE
Boiler	-0.519	-0.145
Wrought iron engine fitting	-0.516	-0.142
Horizontal pipe#	-0.526	-0.152
Cast iron pipe	-0.508	-0.134
Steam pipe	-0.525	-0.136
Stern paddle section	-0.542	-0.170
Base of paddle system	-0.590	-0.216
Wooden deck beam	+0.200	+0.574

* The corrosion potentials were measured against the NSW instrument and this was calibrated against a standard Ag/AgCl reference electrode which had been calibrated against the platinum electrode using a quinhydrone solution buffered at a pH of 4.0. The reference voltage was + 0.374 volts vs. NHE.

This potential was measured using another reference electrode.

The average of all the iron corrosion potentials measured on this site was -0.156 ± 0.028 volts vs. NHE. Part of the reason for the larger standard deviation of these corrosion potentials compared with the previous sites is that with an increased range of water depth, the *Corowa* site can exhibit a wider range of microenvironments. The other major factor is that we note the more anodic (less

negative) potentials associated with the cast iron fittings associated with the engine. The most negative potential was recorded at the base of the paddle system. Given the juxtaposition of the *Corowa* and the *Crowie* it is not surprising to see that they have essentially the same average corrosion potential and the same inherent rate of corrosion.

COBAR: Waikerie

The *Cobar* lies close to Lock 2 on the River Murray about 224 miles from the mouth of the river and about thirteen miles downstream from Waikerie. It was a composite barge that was built in 1882 that was abandoned and sank sometime between 1925 and 1961. Currently the vessel lies parallel to the shore about three metres into the water though in one part the shore almost reaches out to the vessel. Above the waterline the wreck consists of a series of frames with some wooden planking just visible at the waterline, as shown in Figure 106. The water temperature was 11°C. The results of the corrosion potential survey are summarised below in Table 11.

Table 11: Corrosion survey of the barge *Cobar*.

Object	E _{corr.} volts vs. Ag/AgCl	E _{corr.} volts vs. NHE
L shaped stringer, near bow	-0.495	-0.118
Second stringer down, poor condition	-0.387	-0.002
Frame near bow	-0.486	-0.109
Bulkhead	-0.490	-0.113
Corroded frame	-0.269	+0.008
Outside hull plating	-0.489	-0.112
Outside stern plating	-0.479	-0.102
Stern deck plating, badly corroded	-0.286	+0.081
Stern	-0.360	+0.015

*The reference electrode was calibrated in river water against a previously calibrated Ag/AgCl electrode and was +0.377 volts vs. NHE.



Figure 106 View of the exposed frames of the *Cobar* and the stern wheel of the *William Randell*




Figure 107 Pourbaix diagram showing corrosion potentials for materials on the *Jolly Miller*

The mean corrosion potential of the solid iron fittings, frames and plating on the *Cobar* was -0.111 ± 0.006 volts vs. NHE. This average value is higher (more corrosive) than the *Coroiva* and the *Crowie* and this is due in part to the fact that more of the iron in the vessel is protruding from the surface which gives increased access to oxygen and to the setting up of a series of differential aeration cells.

The higher voltage for the submerged stern deck plating of $+0.081$ volts is indicative of a corroded matrix rather than a true corrosion potential reading which requires some solid metal to be in electrical contact with the point of measurement.

The measurement of the corrosion potential of the stern at $+0.015$ is also consistent with this area being heavily corroded since both potentials lie in the domain of the Pourbaix diagram (Pourbaix 1974) where FeO.OH is the thermodynamically stable form of iron. An example of a Pourbaix diagram is shown in Figure 107 where the corrosion potentials for the *Jolly Miller* are plotted. Pourbaix diagrams are thermodynamic plots of stability of metals, metal ions and associated solid phases consisting of corrosion products. Such diagrams are a very convenient way of displaying corrosion data.

WILLIAM R. RANDELL: Waikerie

The *William R Randell* was a wooden paddle steamer built in 1905 and abandoned in the 1930's. It is located in the same area as the *Cobar* and sank during a flood some two kilometres below Lock 2. The only visible part of the vessel is a section of one of the iron paddle frames of the side wheel, as seen in Figure 106. Corrosion measurements were done on fittings associated with the engine and on some of the supporting structural members. Owing to the submerged nature of this vessel it was necessary to use a platinum electrode with the double junction reference Ag/AgCl electrode. Both these electrodes had 15 metre lengths of insulated cables attached to them to facilitate underwater contacts while allowing the digital multimeter to be read on board the work boat. The advantage of the double junction reference electrode is that the isolation of the reference compartment means that the voltage is not sensitive to the chloride content of the local waters.

The salinity data listed in Table 17 shows that the chloride concentration of the river changes significantly and this also affects the voltage of the "flow-through" reference electrodes. The use of the long wires meant that they could be taped to the communications system and the safety line. The pH of the water was 7.61 and the chloride level was 168 ppm (see Table 17). The results of the measurements are shown below in Table 12 where the effects of contact of iron with non-ferrous materials is clearly seen that is the corrosion potentials for the iron fittings connected to brass are elevated by some 144 mV which is probably an increase in corrosion rates of the order of between eight and ten times. The attachment of brass and copper fittings to the iron associated with the boiler will, in the environment of the wreck site, accelerate the corrosion of the associated iron work.

Conservation Assessment

Since the vessel was primarily made of wood the metal corrosion measurements relate to materials associated with the vessels propulsion system. The apparent stable voltages measured for the sight glass on the boiler and for the wooden beam are redox potential measurements, since there is no solid metal present, and the high voltages are consistent with the red-brown patina of iron(III) corrosion products being impregnated into the materials that were measured. If the corrosion products on the wooden beam had been black that would have indicated either magnetite or an iron sulphide - the latter possibilities are also shown to be unlikely because of the positive voltages. The voltage reading of the wooden beam may also in part be due to the presence of dissolved oxygen in the degraded structure. The corrosion potential of -0.045 for the brass fitting on the boiler is typical of material that is corroding in a film free environment with the corrosion products consisting of copper chloride complexes (MacLeod 1992).

Table 12: Corrosion survey of the paddle steamer *William R. Randell*

Fitting	Ecorr. volts vs. Ag/AgCl	Ecorr. volts vs. NHE
Paddle wheel brace	-0.522*	-0.129
Support at wheel base	-0.326	-0.160
Thin plating at top of beam	-0.225	-0.059
Non ferrous, part of boiler	-0.142	-0.024
Iron on boiler with brass fitting	-0.165	-0.001
Possibly glass	+0.167	+0.333
Possibly wooden beam	+0.207	+0.373
Iron hull frame	-0.228	-0.062
Cast iron fitting	-0.219	-0.053

* This measurement was made using the NSW instrument while the rest were made using the remote instruments which were calibrated using the known voltage of a platinum electrode in a saturated quinhydrone solution at a pH of four.

The average corrosion potentials for all the wrought iron materials on the site was -0.102

± 0.052 volts vs. NHE while the cast iron fitting, which was significantly corroded was -0.053 volts. It was noted that only a few of the iron materials measured were in good condition and when these results are averaged the mean corrosion potential for the wrought iron is -0.145 ± 0.022 volts. The differences between the corrosion potentials cannot be easily correlated with site conditions such as water depth because of the practical technical difficulties of determining this measurement when carrying out a survey in blackout conditions. The water depth on the site was dependent on the part of the wreck that was being measured but it generally ranged from 1-3 metres.

J. G. Arnold: Waikerie

The *J.G. Arnold* was built in 1917 at Mannum as a Murray River paddle steamer which came to grief near Waikerie at the 240 mile upstream post near Holder Bend. The pH of the water was measured and found to be 7.61 and the chloride concentration was 168 ppm. The site is fully submerged and the average water depth is six metres. It lies on the outer curve of the river and as such it will be more prone to a localised increase in average water velocity. If the corrosion rate is determined by the flux of dissolved oxygen, as is the case for concreted marine iron, then any factor that increases the flux of dissolved oxygen to the corroding metal will result in an increase in the overall corrosion rate. The results of the survey are shown in Table 13.

Table 13 : Corrosion potentials for the paddle steamer *J.G. Arnold*

Fitting	Ecorr. volts vs. Ag/AgCl	Ecorr. volts vs. NHE
Hull plating	-0.356	-0.190
Corroded deck beam	-0.398	-0.232
Top deck beam	-0.411	-0.245
Wooden beam	+0.244	+0.410
Wooden beam, red coloured surface	+0.247	+0.413
Deck beams	-0.428	-0.262
"T" piece on deck beam for hatch	-0.370	-0.204
Hatch	-0.411	-0.245
Hull material	-0.392	-0.226

Conservation Assessment



The average corrosion potential for the iron fittings in this composite vessel was determined to be -0.229 ± 0.025 volts vs. NHE which is significantly more negative than the average values of the other wrecks listed in the preceding tables. The low voltage is indicative of a low overall corrosion rate. As noted in the discussion for the wooden beams on the wreck of the *William R Randell*, the positive voltages measured on this site are indicative of iron(III) corrosion products impregnated into the wood itself.

JOLLY MILLER: Pyap

The *Jolly Miller* is the oldest iron paddle steamer built in South Australia on the River Murray and it was built in 1866 and it sank near Pyap some time before 1944. It was an iron vessel that was built at Goolwa. The pH of the river water was measured and found to be 7.66 and the chloride concentration of the water was 154 ppm. The site is located near the 298 mile upstream post and some six miles downstream from Loxton. This was the second totally immersed site and the first where the influence of the effects of the silt layer on the corrosion behaviour of the iron was clearly demonstrated. The results of the corrosion survey are noted below in Table 14 and representative values are plotted in the Pourbaix diagram in Figure 107.

Table 14: Corrosion potentials for the wreck of the *Jolly Miller*

Fitting	Ecorr. volts vs. Ag/AgCl	Ecorr. volts vs. NHE
Beam	-0.427	-0.261
Hull plating	-0.437	-0.271
Wrought iron	-0.421	-0.255
Hull plating, out of silt by 20 cm	-0.453	-0.287
Timber planking	+0.268	+0.434
Iron bolt in timber, just out of silt	-0.503	-0.337

The average corrosion potential for all of the iron fittings on the vessel is -0.282 ± 0.014 volts vs. NHE. or -0.268 volts vs. NHE if the value of the iron bolt out of the silt is not included. The average water depth of the site was between 4 and 8 metres with the remains of the vessel resting on the edge of the river bank which falls away quite

quickly once one moves away from the shore line. The low values of the corrosion potentials is indicative of a good state of preservation of this material.

UNDAUNTED/VENTURA II: Berri

This site is located 300m downstream from the waste disposal site at Berri, which is approximately 2 km downstream from the ferry. The pH of the water was 7.67 which seems to be normal for this part of the river system and the chloride level was 113 ppm. Owing to the fact that the remains of the vessels appear to have fallen away from the river bank area off into deeper water there was very little information that was able to be measured on these two contiguous sites. The material that was observed tended to be covered in a layer of silt. The few results from this area are listed below in Table 15.

The average water depth is about 6 metres and it appears that the remains of the vessels have fallen into the steep river bed; at a distance of some ten metres from the shore line a shear drop-off occurs. The average corrosion potential for this site is -0.227 ± 0.016 volts vs. NHE.

Table 15 : Corrosion parameters on the *Undaunted/Ventura* site.

Fitting	Ecorr. volts vs. Ag/AgCl	Ecorr. volts vs. NHE
Concreted deck beam	-0.404	-0.238
Wooden beams	+0.228	+0.394
Deck beam near silt	-0.382	-0.216


Discussion of results

Corrosion potential measurements of submerged and partially submerged wrecks in the River Murray have been performed for the first time. This is the first time that measurements of this type have been performed under *black water* conditions. The use of corrosion potentials to assess the condition of the wrecked barges and paddle steamers will provide heritage managers with a very useful tool for assessing the stability of the metal fittings and fixtures that remain on the sites. One of the practical consequences of this work is that since the turbid waters of the river precludes visual inspection methods, the corrosion measurements can act like a sensitive set of "remote sensing" eyes. Since the traditional methods of assessment cannot



be used in the river, electrochemical measurements can produce an accurate data base to check on changes on site conditions. An example of the use of such data is outlined in the following section.

By plotting the average corrosion potentials for the iron fittings and structural materials, from the different sites, on a Pourbaix diagram it is very easy to appreciate the different nature of the sites at a glance. Some of the data is shown in Figure 108 where some sites with essentially the same average E_{corr.} were omitted for the sake of clarity. When the site parameters are summarised in this form we see that all the average E_{corr.} values for sound iron are in the region of active corrosion. The equilibrium reactions appear to be related to the corrosion of iron to produce Fe²⁺ ions which are in equilibrium with magnetite, Fe₃O₄ according to the following reactions,



The pH of the microenvironment associated with this equilibrium is given by the relationship

$$E_0 = 0.980 - 0.2364 \text{ pH} - 0.0886 \log[\text{Fe}^{2+}] \dots\dots(3)$$

approximately 2.2 ppm Fe²⁺ in equilibrium with magnetite. Assuming that this pH value is typical, the average corrosion potentials on the *Jolly Miller* correspond to approximately 200 ppm Fe²⁺ ions. The individual E_{corr.} measurements on the extensively corroded iron materials on the *William R. Randell* and the *Cobar* are seen to be in the region where FeO.OH is the stable form of iron. This data also is consistent with the observation that these fittings appeared to be extensively degraded. In a similar fashion we see that the voltages recorded for the wooden beams on the *J.G. Arnold*, *William R. Randell* and the *Ventura/Undaunted* are typical of iron(III) corrosion products such as FeO.OH being impregnated into the matrix.

A tabular summary of the average corrosion potentials for the iron fittings and iron structural material on the vessels is found below in Table 16. It is interesting to note that each of the pairs of vessels at each of the main sites at Goolwa, Morgan and Waikerie presented similar values of the corrosion potentials. The more corrosive environment measured for the vessels at Morgan, compared with Goolwa, are probably a reflection of the greater amount of water movement over the wrecks located at Morgan since those at Goolwa were in only what could be described as a very sheltered environment. The average values for the *Cobar* are significantly higher than those measured for the four vessels at Goolwa and Morgan. This is probably due to the much more exposed nature of the metal frames and plates that were being measured.

The more negative values for E_{corr.} found for the vessels upstream of Waikerie and at Loxton and Berri are in part due to the greater depth of water over the sites. It has been observed in the ocean sites that water depth has a major affect on the values of E_{corr.} and, in turn, on the rate of corrosion (MacLeod 1989, p. 2). Although the corrosion mechanism has not yet been validated for river sites, it is most likely that the reduction of dissolved oxygen is involved in the rate determining step in the overall corrosion process. Support for this mechanism is found in the way in which the individual corrosion potentials vary with site conditions. A good example of this is seen on the site of the *Jolly Miller* where the E_{corr.} of the iron in the silt was 82 mV more negative (less corrosive) than values obtained on similar iron sections at a shallower depth which were lying proud of the river bed (see Figure 107).




Figure 108 Pourbaix diagram showing corrosion parameters for wrecked barges and paddle steamers in the River Murray. The symbols used are: Ar(Arnold), Ra(Randell), Ra-Cu(galvanically coupled), Co(Cobar), Cr(Crowie), Al(Albion) and JM(Jolly Miller).

which for the pH of 6.46 observed on the concreted sections on the *Uranus* at Goolwa, gives a ferrous ion concentration of 3.9×10^{-5} M or

Conservation Assessment

Table 16 : Corrosion parameters for wrecks in the River Murray.

Wreck	Water depth (metres)	Ecorr. volts vs. NHE	Nearest town
ALBION	1-2	-0.176±0.025	Goolwa
URANUS	1-2	-0.163±0.007	"
COROWA	2-3	-0.156±0.024	Morgan
CROWIE	1-2	-0.150±0.019	"
COBAR	1-2	-0.111±0.006	Waikerie
Wm. RANDELL	1-4	-0.145±0.052	"
J.G. ARNOLD	6	-0.229±0.025	"
JOLLY MILLER	6-8	-0.282±0.033	Loxton
VENTURA II-UNDAUNTED	4-6	-0.227±0.016	Berri

The changes in the nature of the River Murray water are indicated by the changing pH and chloride content of the water measured on the various sites that ranged from being close to the mouth at Goolwa to being some three hundred miles away at Loxton. The data is dramatically portrayed in Table 17.

Table 17 : The effect of distance from the sea on river water pH and chlorinity.

Nearest town	pH	Distance from the sea miles	[Cl-] ppm.
Goolwa	7.90	5	410
Morgan	7.86	199	185
Waikerie	7.67	224	168
Pyap	7.67	298	154
Berri	7.61	326	113

It is essential that future studies be done on these wreck sites as it will only be possible to assess the stability of the sites by comparing sets of data collected over an extended period. Any parameter that increases the amount of water movement in the area of the wrecks will increase the rate of deterioration of the metals. Examples of avoidable water movements are water skiing where the wash

from the speed boats can have a major effect on the localised site parameters.

An example of the effects of water movement on the preservation of timber is seen in the degradation patterns on the bottom of the P.S. *Colonel*. The timber has apparently been degraded to a much greater extent in the area adjacent to the wash from the paddles than in the sections where the water flow is less turbulent. The iron corrosion products have apparently preserved the wood in the vicinity of the bolts, see Figure 109, whereas iron is normally associated with the increased rate of chemical and biological deterioration. Further work needs to be done to clarify the mechanism of this apparent reaction - the surface profile may also be due to specific biological degradation mechanisms that pertain to the riverine and riparian environments.



Figure 109 Hull planking on the P.S. *Colonel*


Acknowledgments

The assistance, cooperation and patience of my colleagues Bill Jeffery and Sarah Kenderdine is gratefully noted. The trialing of the modified equipment presented more than a few challenges. Without the support of the Trustees of the Western Australian Museum and the permission of the Minister for the Arts, I would not have been able to carry out this very significant project. The financial support of the River Murray Commission is gratefully acknowledged.

Recommendations

- that ongoing monitoring occurs on all selected sites from which data has already been obtained;
- that sites are monitored for the effects of boat wash and specific deterioration of the fabric;

Conservation Assessment



- that documentation of increasing lacunae in site fabric due to boat wash occurs through notation, photography and the collection of other scientific data;
- that evidence from above is used for the declaration of protective zones around vulnerable shipwreck sites;
- that water clarity and quality monitoring is undertaken in the vicinity of wreck sites on a regular basis;
- that the assessment of fluvial dynamics on wreck site deterioration takes place.